

Dyrick Hill Windfarm – Technical Appendix 9.1



Existing Artificial Drainage Channel at Field Boundary near Eastern Area of the Site



Existing Artificial Forestry Drainage Channel Near T05



Existing Artificial Drainage Channel at Field Boundary near Central Area of the Site



The EPA/OSi Mapped Stream North of T04 was not Observed During Field Surveying

Dyrick Hill Windfarm – Technical Appendix 9.1



Potential Wetland Area to the South of T06



Sampling Point 2, an Unnamed Stream North-east of the Forestry Area Near T05



Natural Drainage Channel at the Western Commonage Area with Evidence of Erosion Visible



Sampling Point 3 on the Lisleagh Stream, North of the T01 Area

Dyrick Hill Windfarm – Technical Appendix 9.1



Small Natural Drainage Channel in the Western Commonage Area



Sampling Point 4 on the Upper Reaches of the Aughkilladoon Stream



Sampling Point 5 on the Farnane River, South of the T09 Area



Potential Wetland Area East of the T04 Area

Dyrick Hill Windfarm – Technical Appendix 9.1



Sampling Point 6 on the Farnane River, South-west of the T11 Area



Sampling Point 8 on the Farnane River, South-west of the T10 Area



Existing Gaps in the Forestry Area Near T05



Existing Access Track Near T09 at the Western Commonage Area

Dyrick Hill Windfarm – Technical Appendix 9.1



Existing Drainage Channel at the Western Commonage Area



Pre-Existing Roadside Ponding and Poor Drainage Near the Forestry at T05



Typical Field Boundary Drain at the Central Area of the Site



Sampling Point 12 on the Lisleagh Stream, North-east of the T01 Area